


Installation Instruction for GM 4L80E Transmission Harness with Temperature Sensor

1. Remove old wire harness from valve body.
2. Install new Rostra wire harness.
3. Plug-in connectors as shown in the figure below
NOTE: Use this wiring harness as is with temperature sensor. If existing, leave the current temperature sensor in the valve body unconnected. There is not connector for this sensor.




NOTE: FOR PRE 1993 VEHICLES, EXTERNAL HARNESS MUST BE CONVERTED TO LATER STYLE CONNECTOR USING ROSTRA PART #350-0033, 4L80E EXTERNAL HARNESS REPAIR KIT



Form #4157, Rev. C, 12-03-10

Installation Instruction for GM 4L80E Transmission Harness with Temperature Sensor

1. Remove old wire harness from valve body.
2. Install new Rostra wire harness.
3. Plug-in connectors as shown in the figure below
NOTE: Use this wiring harness as is with temperature sensor. If existing, leave the current temperature sensor in the valve body unconnected. There is not connector for this sensor.




NOTE: FOR PRE 1993 VEHICLES, EXTERNAL HARNESS MUST BE CONVERTED TO LATER STYLE CONNECTOR USING ROSTRA PART #350-0033, 4L80E EXTERNAL HARNESS REPAIR KIT



Form #4157, Rev. C, 12-03-10

Installation Instruction for GM 4L80E Transmission Harness with Temperature Sensor

1. Remove old wire harness from valve body.
2. Install new Rostra wire harness.
3. Plug-in connectors as shown in the figure below
NOTE: Use this wiring harness as is with temperature sensor. If existing, leave the current temperature sensor in the valve body unconnected. There is not connector for this sensor.




NOTE: FOR PRE 1993 VEHICLES, EXTERNAL HARNESS MUST BE CONVERTED TO LATER STYLE CONNECTOR USING ROSTRA PART #350-0033, 4L80E EXTERNAL HARNESS REPAIR KIT



Form #4157, Rev. C, 12-03-10

Installation Instruction for GM 4L80E Transmission Harness with Temperature Sensor

1. Remove old wire harness from valve body.
2. Install new Rostra wire harness.
3. Plug-in connectors as shown in the figure below
NOTE: Use this wiring harness as is with temperature sensor. If existing, leave the current temperature sensor in the valve body unconnected. There is not connector for this sensor.



NOTE: FOR PRE 1993 VEHICLES, EXTERNAL HARNESS MUST BE CONVERTED TO LATER STYLE CONNECTOR USING ROSTRA PART #350-0033, 4L80E EXTERNAL HARNESS REPAIR KIT



Form #4157, Rev. C, 12-03-10